






## Abmessungen (mm)



### Durchflußcharakteristik




### Hysterese




### Zubehör

#### Manometer



Typ:  
G 50. 3/ 6 R  
G 50. 6/10 R  
G 50.10/16 R  
G 50.16/25 R

#### Druckfeder



Typ:  
0,1- 3: C.22-81  
0,2- 6: C.22-82  
0,5-16: C.22-86

#### Mutter

M 42 x 1,5



Typ: C.22-42

#### Winkel



Typ: ZW.22

### Einsatzbeispiel

